



CARE AND MAINTENANCE OF YOUR TRACTION AIDS

STORAGE

- Store in a dry place once completely dry, including the strap.
- Do not store in extreme heat as this could cause damage.



CARE

- Allow straps to dry completely.
- Thoroughly clean the traction aids to remove all visible traces of dirt and salt.



INSPECT

- While cleaning, visually inspect the soles and individual studs for signs of damage, including rips, tears, and uneven wear. Replace any damaged cleats you discover.

Thoroughly clean all visible traces of dirt and salt




Ensure strap stays dry when not in use and allow to dry completely

Store in a dry place, away from extreme heat



Visually inspect the soles and individual studs for signs of damage



HAVE QUESTIONS? TALK TO A TRACTION SPECIALIST TODAY. ICECLEATS.SUREWERX.COM